Christians 76 CHRISTMAS BRISTOL U.K.

FLOWER POWER FLOWER POWER FLOWER POWER FLOWER POWER FLOWER

Issue No.9 The Magazine of the Triumph Mayflower Club Christmas 1976

With the Compliments of the Season from your Committee for 1977

Chairman D.Goodyear, 22 Hayes Close, Newtown, Bristol Vice Chairman T.C.Mills, 33 Woodside Road, Kingswood, Bristol & Spares Sec.

Hon. Sec. Mrs. Eileen Mills, as above.

Hon. Treasurer E. Berry, I3. The Greenway, Fishponds, Bristol Hon Rally Sec. R.K. Varney, 32, Mackie Road, Filton, Bristol

Ord. Member I M.Bath, 3, King Edward Road, Walthamstow, London E 17

Ord. Member 2 R.R.Bussell, Pinnocks, New Road, Tadley, Basingstoke, Hants.

Magazine Ed. R.B.Bussell, also Pinnocks

Archivist P.Burdge, Weeping Ash Farm, Yatton, Somerset.

WHEN WRITING ON CLUB BUSINESS TO ANY OF THE ABOVE PLEASE ENCLOSE S.A.E.

Ed's Piece

As I write this Christmas is still exactly one month away...this becomes my first Christmas card. As it will go this year to at least I48 people and wont cost me any postage, that seems a fair return for the input of effort. Still as Chairman says in his letter, it would be nice to Know what a lot more of you look like. That is one of the drawbacks of a Club like ours. Anyway good luck and prosperity to you in I977 and let us hope that the expected mini-budget does'nt put too much of a damper on Christmas.

Despite the effects of inflation the subscription rates remain the same. ... if we can do it one wonders why so many other organisations seem to accept regular annual increases. I have a feeling that we have become so conditioned to price rises that we no longer stop to consider whether they are really justified. I bet petrol (gas to our U.S. friends) does'nt go down when (and if) the dear old £ regains some of it's value. There really seems no glimmer at the end of the tunnel yet and one wonders where it will all end, or if it ever will. I think Rob's Mayflower will soon have to be converted to one pony-power (anyone got any gash shafts?) whether or not daughter Kim concurs!! Humdrum (the pony) may also have different ideas, but he has no say, although even this is not strictly true as anyone who has been around when we are late with the hay can testify! Still the day could well come when he will be worth all the hay, pony nuts, shoeing and so on that Dad (and Mum) have stumped up for over the last five years or so. The condition of some of our local roads makes one wonder if it will be sooner rather than later. Why is it that with all our modern technology we do not seem to have mastered the problem of refilling a trench to the same level as the adjacent surface?

Enough of our woes, the time of good cheer approacheth! I have tried to make this a real Christmas issue with something of interest to all the family. We even have some articles and notes for the technical this time. My pleas for material have been answered to some extent, for which I am extremely grateful, but keep it coming. And you ladies, let me have contributions for the proposed Ladies Page in future issues...you must all have hints and wrinkles as to picnic meals, motoring clothing, what to do while the men yak about cars, yarns about journeys you will never forget, or even articles about things completely divorced from motoring.

-- 00 --

Will this soon be true?

If computers had existed in the early I800's, before Otto invented his cycle and Daimler and Benz got together, they would probably have predicted that with the population increase expected by now there would be so much horse drawn transport that we would be unable to clear away the manure.

Bristol

Dear Friends.

As I sit writing this letter to you all, I cannot help reflecting on how wonderful it would be if, just once at least, we could all meet together, all I50 odd of us from home and abroad. If only we could—just wishful thinking you say, but dont you believe it! I know it is difficult for our friends overseas and much as we would like it that is, perhaps, hoping for the moon. But how about you here at home. At sometime since you joined the Club you must have wondered who we are and what we are like as people, and why we go to the trouble that we do. We certainly wonder about you. By coming along to the various rallies and outings, and by organising some yourself in the parts of the country that are not so far well catered for, you could satisfy your curiosity (and ours), and enjoy the activities that are, after all, arranged for you.

We fully understand the problems that many of you have, like the cost of petrol and the distance you may have to travel. Would the Pilgrim Fathers in their prototype Mayflower have been daunted by such trivia? I doubt it. So why not give it a swing, boys and girls, next year, you would find your efforts so worthwhile, and make the Committees efforts worthwhile as a result.

With this exhortation ringing in your ears I will now close my letter to you, but not before I wish you all, on behalf of the Committee of the Club, a

Very Happy Christmas and a Prosperous New Year.

Sincerely,

Sgnd. Derek.

Standard Triumph International Rallies.

1976.... Members will be pleased to hear that the rally, which I think all of us who were there enjoyed, has now closed it's accounts and remained in the black - just! This was helped by three clubs (us being one) not putting in a claim for reimbursement for expenditure incurred. We are duly thanked for this gesture. A number of the souvenier plaques and programmes are still available if anyone wants them; 40p for one of each, send cheque payable to S.T.I.R. to Colin Eastwood, 4I Hillside, Lichfield, Staffs.

1977.... John Davey tells us that the response for bookings for a charter flight Jumbo amounted to TWO, so he has cancelled the Jumbo and booked a Tiger Moth! He has reluctantly to say that there is now no chance of a package trip. Still as he succintly observes, with only a sluggish economic recovery predicted and almost inevitably higher taxes it is difficult enough to follow our interest at home, let alone trips to the US. Still, for anyone who can make it we have the following gen:-

S.T.I.R. 2 Venue... Sandpiper Motel, Southampton, New York.

Thursday 2Ist. July (evening) ...Vintage Movies (Films to us!) Friday 22nd. Timed Trials, Bridgehampton Motor Racing Circuit Evening. Museum Tour and Cocktail Party at Long Island Automotive Museum.

Saturday 23rd. Concours Judging and Awards Banquet Sunday 24th. Departure 'Brunch' and Membership Meeting.

During the gathering there will be tech. seminars on spares, restoration, leather, TR and non-TR except on Saturday. All the event will be staged by the Vintage Triumph Register co-hosted by Delaware Valley Triumphs and Long Island Members. There may be some scope for UK visitors to be put up by local members. Send biographic l details to J.B. Davy. Popehill Cottage, Draycote, RUGBY, warks, Before Dec. 31st with SAE.

The 1976 Annual General Meeting... A Brief Report by your Editor.

This year I do not propose to include a full set of Minutes but instead to give you a short report.

The meeting took place at The Royal Oak in Burford on &th. November. Turn out was dissapointing and at I430, the appointed time of starting, only a dozen members were present. This was not even a quorum, the rules requiring I5. Fortunately a few minutes later Malcolm Bath arrived with his contingent and we were just enough! Even the Committee was under strength, both the Hon. Sec. and Treasurer being unable to attend. We hope all is now well.

Chairman kicked off by giving an address drawing attention to the aims of the Club and reviewing how well these were being achieved. He thanked the Committee and members for the help and support he had received in the past year, mentioning particularly the contributions towards the cost of a replacement duplicator. He also mentioned that he had sold his Mayflower and had wondered whether he ought to resign as Chairman. He had however been pursuaded to offer himself for re-election and announced his intention to aquire another 'Flower round about Christmastime.

Terry Mills stood in for both Eileen, Hon Sec, and Treasurer Ted Berry. Eileen obviously derives much pleasure from all the friends made in person and by correspondence. We now have slightly better than I40 members, having lost some 23 along the way. Most of these have not let us know why, they have just let their membership lapse. Terry went through ted's balance sheet (See Flower-Power No. 8, Oct.'76) and there were no queries. Both reports were formally adopted.

Reg gave his Rally Secs Report which reviewed briefly the fun we had had in the past year but bemoaned the poor support at rallies. The loss on the Dodington Rally was much bigger than at first thought, being over £40. He hoped we would do better next year when, without STIR to clash with we could select a better time of year. Attempts at regional gatherings had also been dissapointing, Mrs. Minsall had tried in the North Midlands but no-one had got in touch with her at all. He reported that Leyland Historic Vehicles Ltd. now have a Mayflower in their collection at Donington. We may arrange a 'do' their for the 25th. jubilee of the model. Reg's report was also adopted.

Terry's Spares report followed. We had spares in hand valued at over £380, having during the year bought £700 worth and sold £637 worth. We were doing well as a dollar earner through the sale of spares to our US members. Response to the questionaire with the last issue of FP had so far been poor, only 3 having been received. New spares were becoming more difficult to find and prices were rising as vendors realized their worth. Terry's report was adopted.

Next, as no other nominations were received, on a motion from the floor the entire Committee and Officers of the Club were re-elected en-bloc. On the question of Auditors, those used last year had charged a fee so the Committee were empowered to seek auditors from within the Club who would examine the bboks for free!

Following this, after due discussion of explanations from me as to what they were all about, the proposed rule changes were all formally adopted. This means that we now have a class for Honorary Members, and have given up our power to have a Renown Section. We also now empower the Committee to appoint a Historian, which if you read the last issue of FP you will see they have already done in the excellent choice of Peter Burdge. (To whom welcome to the Committee!)

We then set to to a good natter over sandwiches, sausage rolls and tea.

I should add that I was given the opportunity to make a statement but thi became mainly a plea for contributions. Helen Bath asked for a Ladies Page and was promptly asked to be the first contributor, and Alan Fenton asked if an index of FP could be issued from time to time and for a

AGM Continued.

Back numbers service to be arranged. Both will be adopted, although it may be necessary to make a charge for photo-copying. It largely depended on the demand.

Another item which emerged was that very few requests for reprints of the workshop manual had been received, nothing like the numbers needed for this to be economically viable. Other avenues would be explored. Similarly the process of getting cylinder heads manufactured was proving to be a complex one but was still being pursued... dont give up hope. Particularly short also are trafficators and hubcaps. If members have any 2nd. hand ones for disposal, let Terry know. Most trafficators are interchangeable, only the backplates being different, and hubcaps of any condition will do for replating as long as they are not too seriously pitted or bent. (The posh may prefer to call the hubcaps by the more obscure term 'nave plate' ... what is a nave?).

Phil Hall produced some interesting information regarding ways of circumventing the high cost (for our small numbers) of desirable things like Club ties, window stickers etc. which was refered to the Committee, more news later.

One final and most important point that was aired was that many members may not come to rallies and so on because they feel that their cars are not up to standard. This does not matter one little bit!!! For many if not all of the functions we do not mind what your car looks kike or if you come in the firms Rolls or whatever. We want you to use the Club as a club, not merely a place to get bits and pieces. It is you we want to see, you would be surprised what a load of good fellows we are!!

Woops!! I've just remembered some more! Someone suggested that a list of members prepared to help others who break down in their area be made up and circulated. Two points arise here, one being that to carry out a survey of members, if our usual rate of response to such queries is maintained, would not be much use. The second was that we would hope that any member would help another in difficulty. Thus, as occured about a year ago, a complete list of current members will be drawn up and in due course circulated. Hopefully we are all good Samaritans!

I'm sure there was something else....no, it's gone. If I remember I'll have to stick it in somewhere else.

-- 00 --

Why 'Mayflower'?

The Question has often been asked how our delightful model got it's name. Although the fine detail is probably lost in the mists of time, it does follow a certain trend in Standard Frihmphomodel hametof the times Theolink, of course, is the SEA. Thus both the Renown and the Vanguard were named after warships, both of the steel and wooden wall variety, whilst the names Pennant and Ensign have obviously similar conotations, but all with something of a naval flavour. I would not have thought of the Mayflower as a warship, but it certainly floated! RBB

Flower-Power....You may have noticed that your mag. now only plops through your letter box 4 times a year. There are two reasons for this, the first being that it is difficult to get material and the second is that it costs about £20 per issue in paper and postage. We hpoe members prefer this to a rise in subs. Ed.

Answers to Phil's Christmas Quiz...not to be read until AFTER you have tried to find the answers the hard way. The quiz is on Page 9 7/ Marcos 8/ Ford 9/ Morris IO/ Mustang. I/ Renown 2/ Lotus 3/ Standard 4/ Mayflower 5/ Vanguard 6/ Morgan Answers to Phil's Christmas Juiz. Firstly, welcome to more new members:-

The brass plaques from this year's Rally are still available at 40p each. Car Badges (the Club's elegant standard fitment) are available at £2-I5p each. These make very nice Christmas presents, there should still be time to drop your wife a hint!

The V.T.R. Issue No. IO is a must for Mayflower owners! This is a special Mayflower issue. Contains everything on the model. Price 75p, write to me if you want one, stating Issue No. IO.

The Vintage Triumph Register (of America) mag. covers Triumph Cars from I923 to I967 and is illustrated and written by top British and U.S. authors. It is soon to be in colour. Write to me if you are interested, the current rate is 6 issues for £4-50. (£6 outside U.K.)

Things have begun to slow down a bit now that Winter has arrived, so I'm having it quite easy at the moment. Still if a lot of you take up the offers above I should find things not so quiet again!

Good Wishes to all for Christmas and for 1977.

Eileen

Is Your Mayflower the Right Colour ??? by Frank Lane

Paint news for the purist and the Mayflower owner who must have it right!

These are the manufacturers references for the authentic colours of the Mayflower (plus Black) and the formulae for two of them (I have not been able to obtain the last one).

The makers are General and Industrial Paints Ltd. of 28, Wadworth Road, Perevale, Greenford, Middlesex, and the paints can be ordered through factors.

COTMAN GREY COMET BLUE

Cellulose Ref. 228490

Cellulose Ref. MX 227231

Formula. Formula

| r or mura. | * | | 1 OI MANAGE | |
|------------|--------------|-----|----------------------|-----|
| TXGL.47/I | Dark Grey | 79% | TXGL.47/I Dark Grey | 65% |
| TXGL.18 | Yellow Ochre | 13% | TXGL.I/357Light Blue | 26% |
| TXGL.86/I | Pink Oxide | 4% | TXGL.76 Purple Oxide | 6% |
| TXGL.47 | Black | 4% | TXGL.69 Fast Purple | 3% |

JADE GREEN (METALLIC)

Cellulose Ref. 228127/M ½ hour Synthetic Ref. DY 16423/M

-- 00 --

REWOLFYAM..... Mayflower in reverse? (sorry about that, Ed.)

Here is a quick one for the Ladies, from Ed. It sounds most peculiar, but Oh!, I can feel my taste buds wriggling at the thought of it...

Fry one round of bread per person to a nice crisp golden brown (use new lard or corn oil) and drain off (ie we dont want a lot of soggy fat!)

Spread each piece of fried bread generously with lactic cheese (St.Ivel or Philli)

Slice bananas lengthwise (about 3 for each 2 pieces of bread) and place on the fried bread, (on top of the cheese), covering completely.

Put under grill or in oven just enough to take the chill off the banana but not enough to start melting the cheese.

Squeeze (or squirt) a little lemon juice on the bananas and serve immediately. Try to serve with the bread still piping hot.

Some people grate a little yolk of boiled egg over it .. I've never fancied the thought.

Try it. It is astonishingly good!__ oo --

Roy.

To Him Who Seeks, All Will Be Revealed or words to that effect.

A note by Frank Lane about Mayflower Front Wings.

I wonder if all Mayflower owners are aware of the sealing panels fitted underneath the front wings to protect the underside of the wings (fenders to our US friends, I think, Ed.) from water, grit etc. thrown up by the front wheels.

Personally I was nt until close inspection through the mud and underseal revealed several self-tapping screws holding the panel in position, with a rubber seal abutting the inside of the wing (or mudguard, to use another term, Ed.).

The panels on my car were rusted and broken away so after much application of Plus- Gas (a very penetrating fluid for loosening rusted bolts, screws etc. for those who are unfamiliar with the name) I was able to remove the self tappers and the panels (what was left) and remake from alminium sheet.

The real point of this article is to advise members that I collected half a bucketful of what I can only describe as 'silt' from behind these panels, accumulated I imagine through the lifetime of the car. The tell-tale is rust showing through the lower part of the wings where this deposit rests.

-- co --

Gearbox Operating Transverse Shafts -- Rebushing the Brackets.

David Whyte of 24, Edzell Street, Dundee DD5 3JJ has sent Terry Mills a crafty tool to enable the spherical plasts bushes in which the outer ends of the transverse shafts sit to be replaced without welding. I presume this is available on loan from Terry if you pay the postage. The original bakelite bushes may be difficult to get, if at all, and David says he could make up some nylon ones as replacements. Write to Terry in the first instance.

-- 00 --


CLUB PENS CLUB PENS CLUB PENS.

The Club ballpoint pen, a neat plastic two-tone model, (white and a tasteful combination), writing blue, with Triumph Mayfler Club discretely engraved in gold, are available from Phil Hall, 75, Morley Rd., Staple Hill, Bristol BSI6 4QY at IOp each. Please order in multiples of IO, enclosing payment and an 8½p stamp. Overseas members please write to Phil first for details of postage. These really are handy pens from which Club funds make a slight profit. Buy in bulk for resale to friends and workmates.

The Multi-meter and the Car Enthusiast.

Most of us have, at one time or another, been faced with a failed circuit or an extensive rewiring job. No doubt we have all tapped wire ends onto some convenient piece of bare metal (if we could find one sufficiently paint or rust free) to get a spark. A I2 volt lead acid battery packs quite a wallop and the chances are that at times we have all blown fuses, melted insulation, burnt chromium or fingers in this way. The more advanced practitioner might use a small bulb and length of wire (if he can remember what he did with it after its last use) but even this does not tell him all that much about the circuit other than it is alive or dead!

The right tool to use is one of the simple and modestly priced (£5 or so) multimeters. Many of them cover AC mains voltages and are thus invaluable to the do-it-yourself electrician in the home.



Mine looks something like this and is about this size, and about I" deep

The ranges available on the selector switch are:-

Resistance 0 - I50,000 Ohm

DC Volts 0 - I0, 0-50, 0-250, 0-1000

AC Volts

DC Current 0-I, 0-I00 milliamps.

It contains its own penlite cell for powering the resistance bridge, the zero being set by adjusting the thumbwheel sticking out the side.

Two wandering leads each about I8" long and provided with probes plug into the sockets shown.

It comes in a fairly robust cardboard box, although for some you can get a leather case at extra cost.

It is of course a fairly delicate instrument and must be treated as one or it wont last you very long. For

instance, it wont take kindly to being dropped or getting damp, and it would be somewhat fatal to set it on O-IO volts and put it across a I2 Volt supply!!

The Resistance selection is invaluable for testing:-

Circuit continuity, eg does a switch properly open and close a circuit? Has a length of wire a break in it? Is there a dead short to earth? Is there a high resistance in a circuit (poor earth?)? You can also test bulbs. But whatever you do, dont use this selection on a 'live' circuit with volts present.

The DC Volts selection (0-50) can be used not only to check that volts are present, but also whether a full I2 volts are arriving. Is a switch passing a full I2 volts when 'on' (and sometimes when alledgedly 'off' as well). Also invaluable if not essential when dabbling with voltage control regulators, checking dynamo operation. You can also get a feel for battery condition by noting the volts drop when, for instance, you turn on your headlights.

The milliamps selection is not a lot of use, car currents being in a much higher range. One use I have found is to test for insulation and switch leakage overall. Ensure that everything is shut off, then put the meter in circuit between the battery and one of its terminals.

Multi-meter continued.

Give a merest touch of the probe at first to see if there is much current if any. If the meter does not give a violent kick then make the contact. If all is well the needle should not move. However with a 20 year old the insulation will probably not be perfect and a leakage of a milliamp or two is probably not much to worry about, but keep an eye on it.

The meter will tell you so much about the circuits, and for much of the testing does not even need the car battery to be present. I do not know how I ever got by without one!

R.B.Bussell

00 - 00

En Extreme Cure for a Stuck Brake Piston

Readers might be interested in a method I developed for one of the above on my Renown. The piston was seized firmly in the cylinder and refused to cooperate in any attempts at gentle pursuasion for removal. Thus extreme measures became permissable, it was useless as it was.

Having already removed the cylinder unit from the backplate, the next job was to prize out the steel shoe bearer at the closed end (the Renown cylinder is light alloy). Then a hole, say 3/16" diam., is drilled through the centre of the closed end. Through this a nail with the point cut off or some other suitable punch is passed and attacked with a Scotsmans Screwdriver (to the uninitiated, a hammer) thus driving out the piston. This process wrecks the rubber cup and will also probably damage the plastic button which keeps it in place. Fit a new rubber. The button can be replaced by one of those red plastic closers that come with a Castrol gearoil dispenser after a little minor surgery. However, before assembly, we have to seal the hole we drilled. I did this by a small nut and bolt (head outwards) with a fibre washer such as is used in some carburettors fitted inside the cylinder. Then file down the head as much as you dare, and file a depression in the shoe seat until this can be tapped back into place. Clean everything, making sure particularly that there are no remains from the drilling left inside. The face of the piston may need a little gentle scraping where the nail went. Check that the piston will slide in and out of the cylinder smoothly, souse with brake fluid, reassemble.

If you are lucky and the piston and cylinder are not too sloppy, it will work quite satisfactorily.... mine did!!!

RBB

00)(00

To Construct a Motorists Delight (otherwise known as Bussells Patent Cough Cure and Preventative)

Take a suitable I/3rd pint tumbler or tooth glass.

Into this squeeze the juice of I/2 a lemon, or similar quantity of lemon juice from another source (eg. PLJ, or one of those plastic lemons)

Next add Whiskey, or if you have no Irish you will have to make do with Scotch, but preferably a single malt, at the rate of:-

Child...I tot. Lady...2 tots Gentleman.... Tots.

Now add a generous teaspoon of honey (sugar will do if you have no cough)
Leaving the spoon in the glass, top up with hot water to about I/2 to 2/3 full, stir until the honey is dissolved.

Drink up and to blazes with the cold outside!!!

REPAIRS TO FRONT ENGINE MOUNTS... By Derek Goodyear.

Some months ago I was having difficulty in changing gear on my Mayflower and after a couple of weeks of fearing the worst, ie a faulty gearbox, I noticed that the engine was not sitting straight, having moved slightly to the left from the gearbox end. Investigation showed that the rubber mounting on the gearbox cross member had broken away from the plate, as also had one of the front engine mount rubbers. In this article I explain how I repaired the Front Mounts. In a later one I will deal with the aft mount, which is a bit more complicated.

First remove the offending mount or mounts from the front of the engine, having jacked up the engine first. Note that these mounts are definitely left and right handed, so do not get them mixed up (or their respective bits). Each mount consists of a securing plate which fixes to the engine, a securing plate that fixes onto the chassis, which has two slots in it, plus the central rubber. In my case the rubber was still firmly attached to the chassis plate so I only had the other plate to deal with, but the same procedure could be used for either or both. Put a nut on the welded bolt on the plate and grip in the vise so that plate surface to receive the rubber can be rasped down to clean new metal. Then put the other plate in the vise so that the rubber surface can be rasped down clean and flat. Do not cut away more than is necessary, and if the rubber is contaminated with oil such that it has a spongy texture or is contorted you will have to try to find some new rubber to replace it.

Now put a pinhead sized spot of "Superglue" in each corner of the rubber and press the plate onto it. You have only four or five seconds to complete this manoeuvre and on no account get any glue on the skin (unless you want to wear an engine mount...permanently). Within ten seconds the bond will be secure, and the mount is ready for reuse.

Incidentally, we had earlier, on another local 'Flower, tried another remedy. We purchased from an exhaust depot two large round exhaust mount rubbers (actually Rover) and with a bit of a struggle fitted these to the engine. The result was that the engine was far tactiff and instead of engine movement we had car shake! Be warned!!

PHIL'S CHRISTMAS QUIZ

By Phillip Hall

Find the cars hidden in the following sentences, one in each. In the first the answer is underlined to give you the idea.

- I/ Sir Christopher Wren, owner of a fertile brain, built many of fine London landmarks.
- 2/ To therscotspedevolution to thememeans a ballot, using much gaelic argument to support it.
- 3/ The Tories voted against and ardently argued their case.
- 4/ A river may flow erratically as it wends it's way from source to the other end.
- 5/ The alsatian dog crouched by the caravan, guarding it from all comers.
- 6/ On the farm organic fertilisers are very widely used.
- 7/ In the top dress design houses they have to guard against rival spies, who would do anything to mar costumes and dresses of top designers.
- 8/ Many private landlords live well off ordinary hardworking tenants by their high rent charges.
- 9/ In the Sea of Timor rise many small volcanic islands.
- IO/When trout fishing one must angle the rod at 45 degrees to allow for the flow or to make the artificial fly more attractive to the trout.

Many thanks, Phil. The answers are on Page 4

Does anyone know where to find this in the Bible?

....and Moses came down the mountain in his Triumph.

Rally Secs Notice Board

The old Notice Board is rather empty at present. News of STIR 2 is given elsewhere in this issue, and we have no dates fixed as yet for rallies and meetings at home in 1977. Hopefully all will be made clear in the Spring edition of Flower-Power. Until then, have a good Christmas and all the best for 1977.

Reg.

-- 00 --

Nuts and Bolts Box.

Wiring Diagrams....We are indebted to David Whyte of Dundee for the photostat of the Mayflower wiring enclosed with each copy of this issue of FP. Many thanks David, I'm sure many owners will be delighted with these.

Peter Burdge has added a Vanguard to his collection, which must be quite formidable by now. He comments that it shares many fittings with the Mayflower, like door handles. I seem to remember that the switches were similar, as were the Renown's. I remember my father had a Series I as his first new car after the war and after a nippy but decidedly prewar sprung and silenced I½ litre SS Jaguar D/H it was like driving on air. Later my father had a Series 2 and then an Estate, but neither seemed as good as the beetlebacked Series I. On reflection, that Jag would be worth a few bob now... I seem to remember Dad gave £275 for it in 1939 when it was 2 years old, or was it a 1939 model that was 2 years old when he bought it... no matter, the point is still valid!

While on the subject of memories of family cars, I can just rember Dad's first car, a 2 seater Klino with a dickey seat (in which I, being only 3 or 4 at the time, was not allowed to ride). I thought for years that the dickey seat was where most people carried chickens! This was the only car that Dad has ever written off (he is now 78 and drives one of those great slab sided Zodiacs) His second car was a 4 seat Klino 'tourer' but I do'nt remember that at all. Point is, what happened to all the old Klinos, you hardly ever even here them mentioned these days? I'Ve always understood that the had a solid rear axle without the refinement of a diff. Does anyone have any information on these cars and what happened to the firm?

Peter also suggests that we might include in FP from time to time brief reviews of obsolete books to match our interest in obsolete cars. He says that one of the best 5ps worth he ever bought was "You Have Been Warned-a Complete Guide to the Road" by Fougasse and McCullough, first published by Metheun in 1935. The text is exceedingly witty and is illustrated by cartoons of a very high order. It gives a very comical view of motoring in the 1930s. Quotation is, says Peter, as the book has a style rather like that of "IO66 and all that" and must be seen as a whole to be properly appreciated. He particularly liked the chapter on purchasing a car;

"For instance, if you want an all purpose dependable family car with a great deal of engineering experience behind it, but no frills, we would recommend the Kingston Rattlesnake, of which the makers specification is as follows:-


'Once more Spring's dainty fingers are waking the woods from their winter slumber. Once more the thoughts of the motorist turn with yearning to the countryside, and to the floys that only a RATTLESNAKE can bestow! "

The authors then quote the maker's descriptions of the "Byfleet Polecat" and the "Hampstead Vampire". Strangely, these are exactly the same as the specification of the "Kingston Rattlesnake". Obviously, advertising has not changed much since then!

So, dear friends, keep your eyes open when near the 2nd hand bookshops and see what you can find...and let the rest of us share the fun!

Alternative Lower Wishbone Inner Bushes for your 'Flower, by Robin Bussell.

A Mayflower weakness that MOT inspectors often delight in pointing out is the tendency for the black rubber bushes at the inner end of the lower wishbones of the front suspension to disintegrate. The TR2 sports car, with the virtually identical front suspension, suffered from the same problem—only more so in that the rubbers had rather more vicious stresses to cope with. On the TR3 the rubber bushes and whitemetal washers were changed to an arrangement of steel lined nylon bushes and nylon washers. These modified bushes (see the sketch) can be fitted to the Mayflower.



Each set for one bushing comprises:I steel bush or liner
I nylon bush
2 nylon washers
2 rubber dust seals

For an all-round replacement of the bottom inner bushes four sets are needed. The upper inner bushes can also be replaced in the same way, but here the rubber ones seem to last fairly well and were

dust ring

retained even on the TR3 and TR4 models.

To fit, first of all dismantle the old rubber bush in the normal way. Then clean all the crud and muck off the fulcrum spindle until the steel liner of the new bush is an easy fit. Fit the rubber sealing rings onto the nylon washers. Clean out the eye of the wishbone arm (make a good job of this) until the nylon bush can be pressed into it. Check that the bush has not been distorted so that the steel liner is difficult to introduce. If it is, you've left some crud in the eye...CLEAN IT AGAIN!! To assemble, and to a certain extent this depends on how much you have dismantled the mounting brackets and so on, the liner goes on the fulcrum spindle after a light smear of grease, then one of the nylon washers is slid onto the liner at one end, followed by the wishbone eye containing the nylon bush also lightly smeared with grease. Then the second nylon washer. Discard the metal washer, rut on the mounting plate and bolt up. Remember to replace all tab washers or use nyloc nuts.

These nylon bush sets are probably fairly readily obtainable from Leyland dealers in view of their use well into the '60s on TRs, having started on TR3s after commission No. TS 9121. Another source, and one which I would recammend, is the spare parts shop run by Pete Buckles for the TR Register, at 5I London Road, Tooting, London SWI7 9JR. The shop is open to callers on Thursdays (IO.30 to 2.30), Fridays (IO till 6, lunch I-2), Saturdays (IO till 5, no lunch) and Sundays (IO.30 to 2.30). Other TR3 parts that fit the Mayflower and are usually available are the ball joint (upper wishbone outer end) and the trunnion sub-assembly. It is unlikely that Pete will be able to help with any other Mayflower parts. Buying from the TR shop is likely to cost less than from Leylands but remember that it exists primarily for TR owners and dont expect Pete to be able to answer abstruse 'Flower questions (he is quite busy enough with the TRs). He'll help as much as he can. When ordering parts, mention that you are a member of the Mayflower Club and specify exactly what you want. For enquiries the telephone No. is OI-648-4825.

-- 00 --

Well, there you are folks, that is the Grand Christmas Issue of Flower-Power for 1976, except I think Terry is addind a couple of pages of Spares news. All the best, cheers, and I leave you with this sobering thought:-

Closing date, contributions to next II issue, 12th Warch 1844 this?

The Spares Survey which was included in the last Newsletter, response has been fantastic, 4 only returned to me. Two of these are Americans. Please would you kindly fill them in and return them. Cylinder Heads-remanufactured we are negotiating. Possible source of supply. Cost at present time not known, peoples queries to this tell us it is a number one issue to the car on the road.

HELP NEEDED

Nick Andrews, of New Milton, Bournmouth. Tel. 612174. desperatley wants a good working water pump. If you have a spare one you don't want give him a ring.

For U.S.A. members, spares needed urgently for them. Hub caps, s/hand so long as they can be rechromed. Trafficators, Complete dash panel. So come on start turning out your old spares and give me a ring.

Terry. 0272-675444.

PAINT PATICULARS AND TRIM

Listed below are the official paint specifications, for the Mayflower. Compliments of British Leyland, also the help of Frank Lane.

Black Synthetic) With Beige Dockers Ref. No.) or Red Trim.

Royal Maroon)
Synthetic) Beige Trim.
Dockers Ref. No.)
E. 8688.

Cotman Grey
Synthetic
Dockers Ref. No.
E. 9009.

With Dove Grey
Red Trim.

Manufactured by,

General Industrial Paints Ltd, 28, Wadsworth Road, Penvale, Greenford, Middlesex.

CARS FOR SALE

Miss. Clark. 60, Sandgate Hill, Folkstone, Kent. No details given offers invited.

Mayflower 1952. Running order but in need of restoration. No M. O.T. Realistic offers required. David Freeman, E. S. C. 21, Elmbridge Rd, Gloucester. Tel. 0452-25757

Mayflower 1951. in good condition minor renovation required in running order. Price £200. O.N.O. Janette Eastbrook. 80, Portland Rd, Winton, Bournmouth.

Mayflower 1953. M.O.T. and running order.£100. on.o. Dorian Hancock. 15, Glyme Close, Brookhill, Woodstock, Cxon.

Mayflower 1951 no price given. R.W. McMillen, Transport Manager, A. Monk & Co, P.O. Box 43, Warrington, Cheshire.

Renown. Partially restored spare gearbox, etc etc. Offers Mr. Lere. Rosebud Cottages Coleford, Nr. Radstock, Avon.

SECOND HAND SPARES FOR SALE

SECONDHAND SPARES FOR SALE

- M. Anthony. 329, Duke Rd, Hove, Sussex. Surplus to requirement.

 1) Engine in good condition. 2) Gearboxes. 1) Radiator. 2) Dynamos.
 2) Distributors, also many valvues.
- M. J. Warby. 78, Oxford Rd, Aylesbury, Bucks. 1) Engine 1) Gearbox 1) Ba Backaxle 1) Steering 1) Heater 1) Suspension. Dash& Tyres.

To our fellow members abroad, please be patient, spares will arrive.

The Clubs Workshop Manual can be loaned for a deposite of £3-50 £3. returned when manual has been sent back. Photocopy of different page of this Manual can be done at a price also Spare Parts List.

NEW SPARES IN STOCK HELD BY THE CLUB

| | | " of "shirt for my man and a s | | |
|---------------|---------------------------|--|---------------------------------|--|
| <u>Qty</u> | Part_P | Discription | Price | |
| 6 2 | | Rear handbrake cable Starter cable outer TT11968 on | 2-00 60 | |
| 2 6 | 601021 | Striker plate door | 1-00 | |
| 2 4 | 6 C 1022 TM1 | Front pipe exhust | 1-00 3-5 0 | |
| 10 | TM3 | Tail pipe exhust | 2-50 | |
| 10 | Only AB650 | Front bumpers (includ p & p(Top gasket only | 16-00 3-50 | |
| | CB650 | Complete gasket set out of stock | | |
| Origin. | al pistons | sizes, 020 thou to 060 thou with ring | 20-00 | |
| | ?÷NEW_SPA | RES OBTAINABLE BUT NOT IN STOCK | | |
| 21 | 200826 | Fan | 1-05 | |
| 12 | 201317 | Second speed gear TT24066 onwards | 2-65 | |
| 1 | 300238 30 0 407 | Windscreen wiper motor Gearbox | 11-50 40- 0 0 | |
| 1 | 300612 | Roadwheel TT5554 onward | 4-25 | |
| 53966 | 6 0 0689 | Trunk lid hinge R.H. " " 2 L.H. | 1-45 1-45 | |
| 9 | 600824 | Window regulator handle | 54 | |
| 6 | 601070 6 0 1071 | Door lock TT15068 onward | 1-40 1-25 | |
| 1 | 700297 | Wondscteen | 5-00 | |
| 1 20 | 700426 700520 | Door armrest Locking handle door outside TT15068 | 3-50 2-00 | |
| 4 | 900077 | Heater Unit Front wing panel inner L. H. | 17-0 0 12 - 00 | |
| 3 | CD31262 | Rear quater light vent & class J. H. | 3-50 | |
| 8 | i 31232 KL71469 | Master cylinder Front wheel cylinder to 1951 | 11-50 1 - 50 | |
| • | . 30284 | if if it | 3-25 | |
| | KL71408 35000 | R.H. front wheel cylinder | 1-50 4-00 | |
| | 35001 | L. H. 11 11 | 4-00 | |
| | KL71496 33668 | Front wheel cylinder kits 1951 onwards Rear " " | 70 5 - 00 | |
| | KL71469 | Rear wheel cylinder kits | 1 - 50 2 - 00 | |
| | KL56802 KL56806 | Front brake hose Rear " " | 2-25 | |
| | / LS5 | Front & Rear brake shoes pair | 3-50 | |

These prices were for 1976 May, sothey may be more.

R. Arnokd. of Peacehaven, Bussex. For sale 2, brand new offside inner, Mayflower wings TT No 900018.

A garage at Poole, Dorset. Has written to us offering services of transporting your car by trailer. Charges are 40p per return mile. Radius of 50 miles, contact,

Fernside Road Chevron Srevice Station, Poole, Dorset. BH15 2EW.

CASKIES. VINTAGE AND POST VINTAGE LAME, TRAUTORS, C/VEHIGERS.

D. Cookson. 78, Church Road, Hanwell. London.

Padgets Vintage Car Shares, Welney, Wisbech. Tel Welney 225 & 266 For most parts, including, steering clutch, etc.

Mr. S. J. Moren. -dvance Motor Supelies Limitd, Chesterfield, Derbyshire A various amount of spares for the Mayflower.

Almost all types of mechanical parts can be supplied for Mayflower or Renown. Please quote makers part No, if you don't know, ask us, as we have a parts book in the clubs stock.

T. J. Davis. 27, Julius Gardens, Bramingham Green, Luton, Beds. (Specialists in) King oin sets. Track rod ends. Drag link ends. . De-coke sets. Head maskets. Valv s for 1920 to 1956 cars.

PAINT TRIA PATICULARS

Comet Blue | Jith Dark Synthetic | Docker No | Blue Trim | B. 8451 | Jade Green | Jith Brown Trim | Dockers No | E 9352 |


Additional Information

Member 147. L. A. Ireland, 6, Lawnsmead, Wonersh. Nr. Guildford. Has the lowest T.T. Comm Fo. T.T. 355.

Tember 26. Wr. & Frs. & Hall. 89, Durham Road, Stockton-on-Tees, Cleveland. The highest Comm No. T.T. 33132.

This page is intentionally blank

TRIUMPH "MAYFLOWER" SALOON CARS (1950-51)HOME AND RIGHT HAND DRIVE EXPORT MODELS



KEY TO CABLE COLOURS

I BLUE
2 BLUE with RED
3 BLUE with YELLOW
4 BLUE with YELLOW
5 BLUE with GREEN
6 BLUE with BROWN
8 BLUE with BLACK
9 WHITE
10 WHITE with RED
11 WHITE with YELLOW
12 WHITE with BLUE
13 WHITE with GREEN

KEY TO CABLE COI

14 WHITE with PURPLE
15 WHITE with BROWN
16 WHITE with BLACK
17 GREEN
18 GREEN with RED
19 GREEN with YELLOW
20 GREEN with BLUE
21 GREEN with BLUE
22 GREEN with PURPLE
23 GREEN with BROWN
24 GREEN with BROWN
25 YELLOW with BLUE
37 BROWN with RED
38 BROWN with YELLOW
39 BROWN with GREEN
39 BROWN with GREEN
39 BROWN with GREEN
39 BROWN with PURPLE

40 BROWN with BLACK
41 RED
42 RED with YELLOW
43 RED with BLUE
44 RED with WHITE
45 RED with GREEN
55 PURPLE with BROWN
66 RED with GREEN
67 RED with BROWN
68 RED with BROWN
69 BLACK with YELLOW
69 PURPLE
61 BLACK with YELLOW
69 PURPLE
61 BLACK with WHITE
62 BLACK with WHITE
62 BLACK with WHITE
63 PURPLE with RED
63 BLACK with PURPLE
61 BLACK with WHITE
62 BLACK with WHITE
63 BLACK with WHITE
64 BLACK with WHITE
65 PURPLE with BLUE
66 BLACK with WHITE
67 BLACK with WHITE
68 BLACK with WHITE
69 BLACK with WHITE
69 BLACK with WHITE
60 BLACK with WHITE
61 BLACK with WHITE
62 BLACK with WHITE
63 BLACK with BROWN
64 BLACK with BROWN
65 PURPLE with BLUE

WIRING DIAGRAM No. W77840 12 VOLT

ISSUED:

JUNE 1950

FD/650/L

NUMBERS INDICATE CABLE IDENTIFICATION COLOURS, SEE KEY ABOVE

Printed in England

This page is intentionally blank